













Non-exchangeable pallets:

		A single upper or lower leading board is damaged so that more than one nail or screw shank is revealed.
		A block is missing or split to the point where more than one nail shank is visible.
		A board is broken across its width.
		More than two upper or lower leading boards are damaged and reveal one nail or screw shank for each board.
		A board is missing.
		The (EUR) mark on the right or for example, the (EPAL) symbol on the left is missing.

Other characteristics:

- Fungal decay or insect attack
- Contamination is such that products may be soiled
- Large splinters are coming away from a number of blocks
- There is evidence that inadmissible construction elements have been used, e.g. boards and blocks that are obviously weak

www.epal.eu



EUROPEAN PALLET ASSOCIATION